A3T设备现场布局图
The site layout of A3T









就位要求
Installation requirements

1.整机四周距障碍物至少1m，
The whole machine is at least 1m away from obstacles.

2.整机应远离震源，
The whole machine should be far away from the earthquake source.

3.整机就位场地平整度应不大于5mm，
The leveling of the whole machine should be less than 5 mm.

4.整机接入电压浮动在±5%以内；
The access voltage of the whole machine fluctuates within (+5%).

5.风机及气源请自行放置在不影响使用的位置；
Fans and air sources should be placed in a position that does not affect their use.

6.稳压器、风机为非标设备，若选用，位置请与技术部沟通；
Voltage regulator 、Fans is non-standard equipment. If selected, please communicate with the technical department.

7.外设与电控柜间线缆增加电缆桥架加以保护，
Adding cable bridge to protect cables between peripherals and electronic control cabinets,

8.本布置图的设备位置仅做参考，实际摆放根据现场实际况而定，如有疑问请联系技术人员.
The location of the equipment in this layout is for reference only. The actual layout depends on the actual situation of the site. If you have any questions, please contact the technicians

标记	处数	分区	更改文件号	签名	年 月 日
设计			工艺		
审核			审定		
			批准		

布局图 (Site layout)

济南邦德激光股份有限公司

A3T设备现场布局图

阶段标记	质量	比例
		1:20

A3T-V2.0-XB

共 张 第 张 版本 替代

零件代号
借(通)用件登记
描图
描校
底图总号
底图总号
签字
日期