

PRESS INSPECTION REPORT

Customer							
Press No.	s No. Stock # 2865				o. _	28451	
Model No.	E2-200-72-42			Mfg	g.	Minster	
					_		
1. General Infor	mation						
A. Stroke		10"					
B. Stroke per m	inute	0-90 VSPM					
C. Adjustment of ram		6"					
D. Shut height t	D. Shut height to bed						
2. ELECTRICAL							
A. Operational		Yes	\boxtimes	No [
B. General condition (based on a mechanics observation and not that of an electrician)							
Press is running through controls. Electrical is fully functional.							
3. LUBRICATION							
A. Type of Syste	em	Oil	\boxtimes	Grease [
B. Manufacture	r	Minste	Minster Monitor Flow				
C. All points receive lube			\boxtimes	No [
		-					

D. General condition & assessment

4. PNEUMATICS					
A. Clutch/brake pressure	60 PSI				
B. Counter balance	0 PSI – Missing a Pipe				
C. Cushion	N/A				
D. Check for leaks & note	None				
E. General condition & assessment					
Recommend getting the proper Air	Pipe and Fitting to complete for future customer visits under power.				
5. CLUTCH					
A. Air leak	Yes No 🖂				
B. Travel	Self-contained Self-contained				
C. General condition & assessment		_			
6. BRAKE					
A. Air leak	Yes No 🖂				
B. Travel					
C. General condition & assessment					
<u>Like new – No visible wear</u>					
7. FLYWHEEL BRAKE					
A. Lining thickness	3/8" Thickness				
B. General condition & assessment - OK					
8. GEAR TRAIN					
A. General condition & assessment	,				

9. GUARDS & COVERS							
A. Damage	None						
B. Leaking Oil	Very little						
C. Missing Bolts	No						
D. General Assessment	Good						
10. Main Motor Assemble							
A. Belts Assessment	Good						
B. Shiv & Grooves Assessment	Looks New	Looks New					
C. Motor Mount Assessment	Good	Good					
44 LIVERALILIC OVERLOAD CV	CTERA						
	11. HYDRAULIC OVERLOAD SYSTEM						
A. Operating Pressure	N/A	N/A					
B. Leaks	B. Leaks						
C. General Condition & Assessment							
12. RAM TO BED PARALLELISM							
A. With counter balance pressure on							
Stroke down Stroke up							
LR R	RR	LR	RR				
LF R	RF	LF	RF				
Stroke at 90 degrees		Stroke at 270 degrees					
	RR	LR	RR				
LF R	RF	LF	RF				
B. Condition of slide face	Good						
C. Condition of bolster face Recently Resurfaced by S&G Press Repair							
D. General condition & assessment							

3 of 5

13. GIB CLEARANCE									
A. Points of gibbing		8 Point	8 Point						
B. Front to back									
Bottom of gib				Top	of gib				
LR .002	RR	.002		LR	.005		RR	.005	
LF .005	RF	.005		LF	.002		RF	.002	
C. Left to right									
Bottom of gib				Top	of gib				
LR .002	RR	.005		LR	.002		RR	.005	
LF .003	RF	.005		LF	.003		RF	.004	
D. General condition & assessment									
14. RAM ADJUSTMENT									
A. Limit switches working		Yes	\boxtimes		No				

B. General condition & assessment

Runs smoothly through press controls. Limits not checked

15. RAM LIFT READINGS WITH JAC	CK PRESSURE			
A. Total lift				
LR 040		RR	.041	
LF		RF		
B. Crank shaft or main pin				
LR005		RR	.006	
LF		RF		
C. Connection upper			247	
LR017 Aprox. 24" Bushir		RR RF	.017	
D. Connection lower				
		RR	.007	
LR <u>.007</u> LF		RF		
E. Screw threads				
LR		RR		
LF		RF		
F. Adjustment nut and housing				
LR011		RR RF	.010	
G. General condition & assessmen	t			
16. RUN PRESS				
A. Check for vibration	None			
B. Check for noise	None			
C. Assessment				
Very Good				
17. Serviceman's general overall assessments & comments including repairs				
Appears to be in excellent condition. Install Air Counterbalance Pipes and should be ready to go.				

18. INSPECTION	
Inspected by	Dave Ruthenberg
Date	05/01/2024