HOUSBY INSPECTION REPORT

CONSIGNOR Mitsubishi HC Capital (Illinois) JOB ID 55603

ADMIN

Year Make Model	2022 LIUGONG CLG909ECR
Vehicle Type	Excavator
VIN	LGC909ECTNC130816
Consignor	Mitsubishi HC Capital (Illinois)
Updated Date	10/22/26

VEHICLE INFORMATION

Year	2022
Make	LIUGONG
Model	CLG909ECR
Did It Start?	Yes
Keys	Yes
Jump Batteries	No
Move Status	Pending drop-off
Overall Assessment	Starts, keys: Standard usage wear. Dents/damage to panels. Counter weight scrapped and paint chipping. Thumb cylinder missing of thumb control Engine: Yanmar 4TNV98C 59 HP 19,180 LBS Operating Mass

VEHICLE LOCATION

Street Address	1177 US HIGHWAY 98
City	MCCOMB
State	MS
Zip	39648

VIN TAG

VIN	LGC909ECTNC130816

ENGINE HOUR METER

Hours	508

ANY DAMAGE

Notes	THUMB CYLINDER RIPPED OFF THUMB

HOUSBY INSPECTION REPORT

CONSIGNOR Mitsubishi HC Capital (Illinois)

JOB ID 55603




















LiuGONG





HOUSBY INSPECTION REPORT

CONSIGNOR Mitsubishi HC Capital (Illinois) **JOB ID** 55603
















HOUSBY INSPECTION REPORT

CONSIGNOR Mitsubishi HC Capital (Illinois)

JOB ID 55603















HOUSBY INSPECTION REPORT

CONSIGNOR Mitsubishi HC Capital (Illinois)

JOB ID 55603



