



HOUSBY INSPECTION REPORT

CONSIGNOR Mitsubishi HC Capital (Illinois)

JOB ID 53058

ADMIN

Year Make Model 2022 BELL B45E
Vehicle Type Dump Truck
VIN B93A645EC03007852
Consignor Mitsubishi HC Capital (Illinois)

VEHICLE INFORMATION

Year 2022
Make BELL
Model B45E
Move Status Not moving
Overall Assessment STARTED ON SITE RF and RR tires have sidewall damage

VEHICLE LOCATION

Street Address 8111 MILLS ROAD
City HOUSTON
State TX
Zip 77064

VIN TAG

VIN B93A645EC03007852
Wheel Base 180

D/S FRONT CORNER

Shipping Length 420
Shipping Width 120
Shipping Height 140

LEFT FRONT TIRE

Wheel Type Steel
Tire Size 29.5R25

RIGHT FRONT TIRE

Notes Sidewall damage
Wheel Type Steel
Tire Size 29.5R25

RIGHT SIDE BODY

Body Composition Steel
Body Length 240
Tarp System No

RIGHT REAR TIRE

Notes Rear - Sidewall damage
Wheel Type Steel
Tire Size 29.5R25

LEFT REAR TIRE

Wheel Type Steel
Tire Size 29.5R25

ENGINE TAG

Engine Make MERCEDES
Engine Model 12.0
Serial Number 0679371

DASH SHOT

Did It Start? Yes
Keys Yes
Jump Batteries No
Starting Fluid No
PTO No
Type of Other
Transmission
Air Conditioning Yes
Warning Lights No



HOUSBY INSPECTION REPORT

CONSIGNOR Mitsubishi HC Capital (Illinois)

JOB ID 53058

BODY CONTROLS

Backup Camera Yes

ENGINE HOUR METER

Hours 5997

CONSIGNOR Mitsubishi HC Capital (Illinois)

JOB ID 53058



CONSIGNOR Mitsubishi HC Capital (Illinois)

JOB ID 53058

