



# HOUSBY INSPECTION REPORT

CONSIGNOR Mitsubishi HC Capital (Illinois)

JOB ID 56973

## ADMIN

Year Make Model 2019 FREIGHTLINER CASCADIA 126  
Vehicle Type Retail Sleeper  
VIN 3AKJHHDR3KSKK8173  
Consignor Mitsubishi HC Capital (Illinois)

## VEHICLE INFORMATION

Year 2019  
Make FREIGHTLINER  
Model CASCADIA 126  
Overall Assessment Starts w/ jump; keys (we ordered); In Derate; warning lights - CEL; Stop Engine; TC ; rust on air tanks; tires worn; p/s scratched and dented; cab mirror damaged on p/s; missing p/s fariring extension - brackets broken; p/s steps dented; p/s rear lower corner dented in;

## VEHICLE LOCATION

Street Address 815 EDMONDS AVENUE  
City MCCRORY  
State AR  
Zip 72101

## VIN TAG

VIN 3AKJHHDR3KSKK8173  
Wheel Base 200"  
Front Axle Weight 12350  
Rear Axle Weight 40000

## D/S FRONT CORNER

Shipping Length 330"  
Shipping Width 102"  
Shipping Height 144"  
Damage/Defects? No

## D/S STEER TIRE

Wheel Type Steel  
Tire Size 295/75R22.5  
Damage/Defects? No

## D/S STEER TREAD

D/S Steer Tread 9/32

## D/S OIL PAN

Visible Leak? No

## HEAD ON

Damage/Defects? No

## P/S FRONT CORNER

Damage/Defects? No

## P/S STEER TIRE

Wheel Type Steel  
Tire Size 295/75R22.5  
Damage/Defects? No

## P/S STEER TREAD

P/S Steer Tread 10/32



# HOUSBY INSPECTION REPORT

CONSIGNOR Mitsubishi HC Capital (Illinois)

JOB ID 56973

## P/S OIL PAN

Visible Leak? No

## P/S CAB CLOSE UP

Fuel Tank Composition Aluminum  
Fuel Tank Capacity 120  
Damage/Defects? No

## TRANSMISSION

Visible Leak? No

## DRIVESHAFT

Damage/Defects? No

## P/S SIDE PROFILE

Notes Damage to right rear of cab - sleeper  
Damage/Defects? No

## P/S DRIVE TIRES

Wheel Type Steel  
Tire Size 295/75R22.5  
Damage/Defects? No

## P/S AXLE 1 IN DEPTH

P/S Axle 1 Inner Depth 8/32

## P/S AXLE1 OUT DEPTH

P/S Axle 1 Outer Depth 6/32

## P/S AXLE 2 IN DEPTH

P/S Axle 2 Inner Depth 9/32

## P/S AXLE2 OUT DEPTH

P/S Axle 2 Outer Depth 7/32

## P/S REAR SUSPENSION

Type of Suspension Air Ride  
Damage/Defects? No

## P/S REAR CORNER

Damage/Defects? No



# HOUSBY INSPECTION REPORT

CONSIGNOR Mitsubishi HC Capital (Illinois)

JOB ID 56973

## REAR

Damage/Defects? No

## D/S REAR CORNER

Damage/Defects? No

## D/S DRIVE TIRES

Wheel Type Steel  
Tire Size 295/75R22.5  
Damage/Defects? No

## D/S AXLE 1 IN DEPTH

D/S Axle 1 Inner Depth Less than 2/32

## D/S AXLE1 OUT DEPTH

D/S Axle 1 Outer Depth 10/32

## D/S AXLE 2 IN DEPTH

D/S Axle 2 Inner Depth 10/32

## D/S AXLE2 OUT DEPTH

D/S Axle 2 Outer Depth 13/32

## D/S REAR SUSPENSION

Type of Suspension Air Ride  
Damage/Defects? No

## 5TH WHEEL

Fifth Wheel Type Air Slide  
Damage/Defects? No

## D/S CAB CLOSE UP

Fuel Tank Composition Aluminum  
Fuel Tank Capacity 120  
Wet Kit No  
Damage/Defects? No

## D/S SIDE PROFILE

Sleeper Size 63  
Damage/Defects? No

## 3 INTERIOR PICS

Damage/Defects? No



# HOUSBY INSPECTION REPORT

CONSIGNOR Mitsubishi HC Capital (Illinois)

JOB ID 56973

## 3 SLEEPER PICS

Damage/Defects? No

## 3 DASH PICS

PTO No  
Air Conditioning Yes  
Damage/Defects? No

## SHIFT PATTERN

Type of Automatic  
Transmission

## ODOMETER

Miles 683488  
Miles / KM? Miles

## ENGINE HOUR METER

Hours 22700

## MECHANICAL NOTES

Notes batteries are bad  
Did It Start? Yes  
Keys Yes  
Jump Batteries Yes  
Starting Fluid No  
Warning Lights Yes  
Damage/Defects? No

## D/S ENGINE

Damage/Defects? No  
Oil in Coolant? No

## ENGINE OIL DIPSTICK

Milky? No

## P/S ENGINE

Damage/Defects? No  
DPF Functional? Yes

## ENGINE TAG

Engine Make Detroit  
Engine Model DD15  
Horse Power 505  
Engine Serial 47291050589248



# HOUSBY INSPECTION REPORT

CONSIGNOR Mitsubishi HC Capital (Illinois)

JOB ID 56973





JOB ID 56973

