HOUSBY INSPECTION REPORT

CONSIGNOR Mitsubishi HC Capital (Illinois)

JOB ID 59997

ADMIN

Year Make Model	2023 HYUNDAI HL970A
Vehicle Type	Wheel Loader
VIN	HHKHWL70LL0000323
Consignor	Mitsubishi HC Capital (Illinois)
Updated Date	10/07/26

VEHICLE INFORMATION

Year	2023
Make	HYUNDAI
Model	HL970A
Unit Number	5662
Move Status	Moved
Processed?	Yes
Overall Assessment	Starts; keys; rust and normal wear
Did you D-ID this item?	yes

VEHICLE LOCATION

Street Address	506 N. ELLIS AVENUE
City	DUNN
State	NC
Zip	28334

VIN TAG

VIN	HHKHWL70LL0000323

LEFT FRONT TIRE

Wheel Type	Steel
Tire Size	26.5R25

HEAD ON BUCKET

Bucket Width	126
Bucket Capacity	9

RIGHT FRONT TIRE

Wheel Type	Steel
Tire Size	26.5R25

RIGHT SIDE BODY

Body Type	Enclosed ROPS

RIGHT REAR TIRE

Wheel Type	Steel
Tire Size	26.5R25

LEFT REAR TIRE

Wheel Type	Steel
Tire Size	26.5R25

ENGINE TAG

Engine Make	CUMMINS
Engine Model	L9
Horse Power	330
Serial Number	22589501
Fuel Type	Diesel

ENGINE OIL DIPSTICK

Milky?	No

HOUSBY INSPECTION REPORT

CONSIGNOR Mitsubishi HC Capital (Illinois)

JOB ID 59997

DASH SHOT


Did It Start?	Yes
Keys	Yes
Jump Batteries	No
Type of Transmission	Other
Air Conditioning	Yes
Warning Lights	No
Heat	Yes

ENGINE HOUR METER


Hours	6,899

HOUSBY INSPECTION REPORT


CONSIGNOR Mitsubishi HC Capital (Illinois) **JOB ID** 59997


























HOUSBY INSPECTION REPORT


CONSIGNOR Mitsubishi HC Capital (Illinois) **JOB ID** 59997

























HYUNDAI


PM 02:41
lb 0.0
Total B lb 0.0
A DAYS FUEL USED 0.1 gal
LATEST HOUR METER 6,899.8 Hr
ENGINE MODE POWER
C.C.O. Mode L
SHIFT MODE AH
798 rpm
ECO
MENU HOME
ESC

HOUSBY INSPECTION REPORT

CONSIGNOR Mitsubishi HC Capital (Illinois) **JOB ID** 59997





