



HOUSBY INSPECTION REPORT

CONSIGNOR Mitsubishi HC Capital (Illinois)

JOB ID 57813

ADMIN

Year Make Model 2022 HYUNDAI HX235ALCR
Vehicle Type Excavator
VIN HHKHK608EE0000163
Consignor Mitsubishi HC Capital (Illinois)

ANY DAMAGE

Notes WARE AND TEAR FROM USE, NO MAJOR DENTS OR VISIBLE DAMAGE. MOSTLY SCRAPES/SCRATCHES ON BODY/BOOMS/BUCKET.

VEHICLE INFORMATION

Year 2022
Make HYUNDAI
Model HX235ALCR
Unit Number 20652
Did It Start? Yes
Keys Yes
Jump Batteries No
Move Status Moved
Processed? Yes

VEHICLE LOCATION

Street Address 11139 S TAMiami TRAIL
City PUNTA GORDA
State FL
Zip 33955

VIN TAG

VIN HHKHK608EE0000163

BUCKET SERIAL TAG




Notes PN: EX20HD42 SN: 0044225-1-1 MOD:
HYUNDAI HX220A CAP: 1 22 CY CAP PO#:
AA22291 OPTION: 1U3352

ENGINE HOUR METER

Hours 3495.5




CONSIGNOR Mitsubishi HC Capital (Illinois)

JOB ID 57813








CONSIGNOR Mitsubishi HC Capital (Illinois)

JOB ID 57813



CONSIGNOR Mitsubishi HC Capital (Illinois)

JOB ID 57813



CONSIGNOR Mitsubishi HC Capital (Illinois)

JOB ID 57813

