HOUSBY INSPECTION REPORT

CONSIGNOR Mitsubishi HC Capital (Connecticut) JOB ID 57935

ADMIN

Year Make Model	2023 LIUGONG 838 HV
Vehicle Type	Wheel Loader
VIN	CLG838HVPPL701867
Consignor	Mitsubishi HC Capital (Connecticut)

VEHICLE INFORMATION

Year	2023
Make	LIUGONG
Model	838 HV
Unit Number	WHOLESALE
Move Status	Moved

VEHICLE LOCATION

Street Address	1407 FM 1462
City	ALVIN
State	TX
Zip	77511

VIN TAG

VIN	CLG838HVPPL701867

LEFT FRONT TIRE

Wheel Type	Steel
Tire Size	20.5R25

HEAD ON BUCKET

Bucket Width	106”
Bucket Capacity	3.0

RIGHT FRONT TIRE

Wheel Type	Steel
Tire Size	20.5R25

RIGHT REAR TIRE

Wheel Type	Steel
Tire Size	20.5R25

LEFT REAR TIRE

Wheel Type	Aluminum
Tire Size	20.5R25

ENGINE TAG

Engine Make	CUMMINS
Engine Model	B4.5
Horse Power	154
Serial Number	22567775
Fuel Type	Diesel

DASH SHOT

Did It Start?	Yes
Keys	Yes
Jump Batteries	No
Type of Transmission	Automatic
Air Conditioning	Yes
Warning Lights	No
Heat	Yes

ENGINE HOUR METER

Hours	499

HOUSBY INSPECTION REPORT

CONSIGNOR Mitsubishi HC Capital (Connecticut)

JOB ID 57935

























HOUSBY INSPECTION REPORT

CONSIGNOR Mitsubishi HC Capital (Connecticut) **JOB ID** 57935















HOUSBY INSPECTION REPORT

CONSIGNOR Mitsubishi HC Capital (Connecticut)

JOB ID 57935







