HOUSBY INSPECTION REPORT

CONSIGNOR Mitsubishi HC Capital (Connecticut) JOB ID 57940

ADMIN

Year Make Model	2023 LIUGONG 848HV
Vehicle Type	Wheel Loader
VIN	CLG848HVVPL701869
Consignor	Mitsubishi HC Capital (Connecticut)

VEHICLE INFORMATION

Year	2023
Make	LIUGONG
Model	848HV
Unit Number	WHOLESALE
Move Status	Dropped off
Overall Assessment	Starts; keys; normal usage wear/tear; rust on bucket

VEHICLE LOCATION

Street Address	1407 FM 1462
City	ALVIN
State	TX
Zip	77511

VIN TAG

VIN	CLG848HVVPL701869

LEFT FRONT TIRE

Wheel Type	Steel
Tire Size	20.5R25

HEAD ON BUCKET

Bucket Width	114”
Bucket Capacity	3.6

RIGHT FRONT TIRE

Wheel Type	Steel
Tire Size	20.5R25

RIGHT SIDE BODY

Body Type	Enclosed ROPS

RIGHT REAR TIRE

Wheel Type	Steel
Tire Size	20.5R25

LEFT REAR TIRE

Wheel Type	Steel
Tire Size	20.5R25

ENGINE TAG

Fuel Type	Diesel

DASH SHOT

Did It Start?	Yes
Keys	Yes
Jump Batteries	No
Type of Transmission	Automatic
Air Conditioning	Yes
Warning Lights	No
Heat	Yes

HOUSBY INSPECTION REPORT

CONSIGNOR Mitsubishi HC Capital (Connecticut)

JOB ID 57940

ENGINE HOUR METER

Hours	902

HOUSBY INSPECTION REPORT

CONSIGNOR Mitsubishi HC Capital (Connecticut) **JOB ID** 57940

























HOUSBY INSPECTION REPORT

CONSIGNOR Mitsubishi HC Capital (Connecticut) **JOB ID** 57940















HOUSBY INSPECTION REPORT

CONSIGNOR Mitsubishi HC Capital (Connecticut)

JOB ID 57940





